

ENGINEERING BULLETIN

Ref Document No.	EB15018	Issue No.	1
Subject	COALTRAM® Service Sheets		
Release Date	20 th November 2015		

Purpose – Advise COALTRAM® owners and operators of updated service sheets for maintenance of COALTRAM®.

Applicability – All in service COALTRAM® models – CT08, CT10, CT10LP

Information

In an effort to reduce service costs of the COALTRAM®, PPK have modified some tasks and removed some items from the service sheets and service kits that were thought to be unnecessary.

The updated service sheets with specific modifications are listed below:

- Mechanical
 - Code C1 / 500 hour – replacement of engine breather changed to cleaning of breather, removal of fluid sampling. Engine breather and sample bottles removed from service kit.
 - Code C2 / 1000 hour – replacement of engine breather changed to cleaning of breather. Engine breather removed from service kit.
 - Code D1 / 4000 hour – PPK now offer overhauled as well as new turbos. This service sheet has changed to recommend replacing or overhauling the turbo.
 - Code D2 / 8000 hour – PPK now offer overhauled as well as new turbos. This service sheet has changed to recommend replacing or overhauling the turbo.
- Electrical
 - Electrical Periodic Inspection, 6 Monthly – Removed the requirement to disconnect and clean all sensor IS connectors if cable tie is installed around sensor weather boot.

Recommendations

PPK recommend reviewing existing maintenance tasks completed during scheduled servicing against those recommended in the attached service sheets.

Ashley Ryan
Mechanical Engineer

PPK Mining Equipment Pty Ltd
 T: +612 4964 5400
 E: a.ryan@ppkgroup.com.au
www.ppkgroup.com.au