

ENGINEERING BULLETIN

Ref Document No.	EB17001	Issue No.	1
Subject	COALTRAM® Service Sheets		
Release Date	21 st February 2017		

Purpose – Advise COALTRAM® owners and operators of updated mechanical service sheets for maintenance of the COALTRAM®.

Applicability – All in service COALTRAM® models – CT08, CT10, CT10LP

Information

PPK are continually looking to improve and tailor the service sheets to include only necessary tasks and inspections. In response to reports around wear in the steering column bearing as the COALTRAM® ages, the mechanical service sheets have been updated with some specific checks.

The updated service sheets with the specific inclusions listed below:

- Mechanical – Cab Section
 - 500 & 1,000 hour:
 - inspect steering column bearing condition, operation and longitudinal movement.
 - 2,000, 4000 & 8,000 hour:
 - inspect steering column bearing condition, operation and longitudinal movement.
 - Inspect steering wheel and spinner condition and operation

Recommendations

PPK recommend reviewing existing maintenance tasks completed during scheduled servicing against those recommended in the attached service sheets.

Ashley Ryan
Mechanical Engineer

PPK Mining Equipment Pty Ltd
 T: +612 4964 5400
 E: a.ryan@ppkgroup.com.au
www.ppkgroup.com.au