

Technical Bulletin / Safety Alert

Unique ID No: DES2011-TBSA-03 Rev: 1

Subject: MDA DES13017 - Part Number Updates

Date: 7/06/2011

Applicable to: MDA DES13017 Diesel Engine Systems (Driftrunners & Brumbies)

Details of Revision: 0. Original Issue

1. Exhaust Adapter Part No. Corrections

Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

Description:

Valley Longwall International Diesel Division (VLIDD) wish to advise of the following MDA DES13017 part number updates:

New Part No.	Previous Part No.
9-04100116	9-04100104
9-04160114	9-04160106
5-04112601	5-04100602
	9-04160114

The above part number changes are administrative changes only and the integrity of the components with respect to MDA DES 13017 compliance has in no way been affected.

The relevant DES general arrangement drawings have been updated to reflect these changes and are attached for reference.

Supporting Documentation:

MDA DES 13017 GA drawings 4-041002, 4-041007 and 4-041069.

DES2011-TBSA-03 Page 1 of 2

Please ensure this document is circulated to all relevant personnel within your organisation.

Should you have any further queries please contact your VLI Diesel Representative.

Tomago Operation 28 Old Punt Road Tomago NSW 2322 P: +61 2 4913 7500 F: +61 2 4964 8919 Rutherford Operation 20 Shipley Drive Rutherford NSW 2320 P: +61 2 4015 3200 F: +61 2 4932 1722 Mackay Operation 6 Fursden Street Glenella QLD 4740 P: +61 7 4942 7495 F: +61 7 4942 4944 Emerald Operation 44 Industrial Drive Emerald QLD 4720 P: +61 7 4987 5011 F: +61 7 4987 4711

DES2011-TBSA-03 Page 2 of 2