

Technical Bulletin / Safety Alert

Unique ID No	: DES-2017-TBSA-01	Rev: 0
Subject	: MDR090376DES – Fas	steners – Inlet Flametrap Housing
Date	:28 th June 2017	
Applicable to	: VLI Driftrunner & Brumby Machines and Diesel Engine Systems currently complying to: MDR 090376 DES - all	
Details of Revision	: 0 - Original Issue	

Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

Description:

There have been a number of reported incidents where inconsistent fasteners are being utilised in and around the Intake Flametrap Housing on the above DES.

Review:

VLI carried out an internal assessment of Design Registered Approvals, associated drawings, VLI Mechanical Code D Documentation & Parts Manuals in relation to fasteners used in the MDR 090376 DES.

VLI concluded that there were inconsistency's in some of the Parts Manuals.

Recommendations:


VLI recommend that the correct fasteners are used in all joints associated with MDR DESs.

Please refer to the below extract from the Parts Manual for correct Part Number.

Stainless Steel Fasteners are not recommended to be used in either of these below joints.

Please ensure this document is circulated to all relevant personnel within your organisation.

Should you have any further queries please contact your VLI Representative.



Beresfield 8 Balook Drive Beresfield NSW 2322 P: +61 2 4964 2300 F: +61 2 4028 6796 Emerald 44 Industrial Drive Emerald QLD 4720 P: +61 7 4987 5011 F: +61 7 4987 4711