



Technical Bulletin / Safety Alert

Unique ID No: DES2014-TBSA-06

Rev: 0

(This document supersedes all previous versions of DES2014-TBSA-06)

Subject: MDA DES 13017 Component Flamepath Drawing Revisions

Date: 5th December 2014

Applicable to: MDA DES13017 Diesel Engine Systems (Driftrunners & Brumbies)

Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

Notification:

VLI advises the following MDA DES13017 component flamepath drawing revisions:

| Drawing No. | Revision | Drawing Description |
|--------------------|-----------------|---|
| 4-041001 | 3 | 1006-6 DES (MDA DES 13017) Component Flamepaths |
| 4-041006 | 2 | 1006-6 DES (MDA DES 13017) Component Flamepaths |

The abovementioned drawing revisions were completed to address typographical errors and align component reference dimensions with components common to other diesel engine systems. These drawing changes were administrative changes only and there have been no design changes to the MDA DES 13017 diesel engine system. Drawing copies are attached to this TBSA.

Please ensure this document is circulated to all relevant personnel within your organization. Should you have any further queries please contact your VLI Representative.

Beresfield
8 Balook Drive
Beresfield NSW 2322
P: +61 2 4964 2300
F: +61 2 4028 6796

Mackay
6 Fursden Street
Glenella QLD 4740
P: +61 7 4942 7495
F: +61 7 4942 4944

Emerald
44 Industrial Drive
Emerald QLD 4720
P: +61 7 4987 5011
F: +61 7 4987 4711

Unanderra
3 Investigator Drive
Unanderra NSW 2526
P: +61 2 4220 9400
F: +61 2 4272 5530

Mudgee
24A Industrial Avenue
Mudgee NSW 2850
P: +61 2 6372 9847
F: