



Technical Bulletin / Safety Alert

Unique ID No: GEN2014-TBSA-02 **Rev:** 0

(This document supersedes all previous versions of GEN2014-TBSA-02)

Subject: JUG-A-0 PTO Return Filter Housing Guard

Date: 11th September 2014

Applicable to: ALL VLI JUG-A-0 UL/UV Machines (Where Installed)

Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

Notification:

In response to a recent customer request, VLI advises the availability of an optional protective guard for the PTO Return Filter Housing installation on JUG-A-0 UL/UV Machines (where installed).

The PTO Return Filter Housing, where installed, is located on the top of the hydraulic oil tank, is of a cast aluminium construction and is potentially exposed to damage. The housing is currently protected via protective coating. The addition of the guard provides an increased level of protection.

The images in Figure 1 provide a representation of the PTO Return Filter Housing, the optional guard and an exploded view of the guard installation.

| VLI Part Number | Description |
|------------------------|---------------------------------|
| 0508-60217 | PTO Return Filter Housing Guard |

The installation of the new guard requires modification to the top of the hydraulic oil tank, and therefore it is recommended to contact VLI to discuss options for the installation of this guard.




Figure 1: Images showing the PTO Return Filter Housing a) as installed without guard, b) as installed with guard and c) an exploded view of the guard installation.

Please ensure this document is circulated to all relevant personnel within your organization. Should you have any further queries please contact your VLI Representative.

Beresfield
8 Balook Drive
Beresfield NSW 2322
P: +61 2 4964 2300
F: +61 2 4028 6796

Mackay
6 Fursden Street
Glenella QLD 4740
P: +61 7 4942 7495
F: +61 7 4942 4944

Emerald
44 Industrial Drive
Emerald QLD 4720
P: +61 7 4987 5011
F: +61 7 4987 4711

Unanderra
3 Investigator Drive
Unanderra NSW 2526
P: +61 2 4220 9400
F: +61 2 4272 5530

Mudgee
24A Industrial Avenue
Mudgee NSW 2850
P: +61 2 6372 9847
F: