



## **Technical Bulletin / Safety Alert**

**Unique ID No:** GEN2013-TBSA-01

**Rev:** 0

(This document supersedes all previous versions of the above TBSA)

**Subject:** VLI Driftrunner F & G Series – Service Sheets

**Date:** 15<sup>th</sup> March 2013

**Applicable to:** VLI Driftrunner F & G Series

**Note:** Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

### **Action:**

VLI Diesel advises the release of revised Service Sheets applicable to VLI Driftrunner F & G Series vehicles.

### **Supporting Documentation:**

- OPER-15018-1 – Daily Inspection – Driftrunner F & G Series - Rev 2
- OPER-15018-2 – 50 Hour Service – Driftrunner F & G Series - Rev 2
- OPER-15018-3 – 250 Hour Service – Driftrunner F & G Series - Rev 3
- OPER-15018-4 – 500 Hour Service – Driftrunner F & G Series - Rev 3
- OPER-15018-5 – 1000 Hour Service – Driftrunner F & G Series - Rev 3
- OPER-15018-6 – (Shiftly) Prestart Inspection – Driftrunner F & G Series – Rev 0

Please ensure this document is circulated to all relevant personnel within your organisation.

Should you have any further queries please contact your VLI Diesel Representative.

Beresfield Operation  
8 Balook Drive  
Beresfield NSW 2322  
P: +61 2 4964 2300  
F: +61 2 4028 6796

Mackay Operation  
6 Fursden Street  
Glenella QLD 4740  
P: +61 7 4942 7495  
F: +61 7 4942 4944

Emerald Operation  
44 Industrial Drive  
Emerald QLD 4720  
P: +61 7 4987 5011  
F: +61 7 4987 4711