

Engineering Bulletins			
Doc #	Date	Description	Rev #
EB13001	12/03/2013	Procedural changes to installation of turbo	1
EB13002	11/11/2013	Exhaust Manifold to Turbo Connection	1
EB13003	11/11/2013	Radiator Cleaning Access	1
EB13004	24/04/2015	Radiator Design Change	2
EB13005	11/11/2013	Front Drive shaft loop	1
EB13006	11/11/2013	Particulate filter housing	1
EB13007	19/11/2013	Relief valve on MONEx Shutdown system	1
EB15001	09/01/2015	Hydraulic return hose in Articulation	1
EB15002	03/09/2015	Load frame Pins	2
EB15003	16/02/2015	Sealing of Deutsch Connectors used on the MONEx System	1
EB15004	19/02/2015	Caterpillar Electronic Injector Unit Trim Files	1
EB15005	16/04/2015	Exhaust Back Pressure Sensor	2
EB15006	14/05/2015	Start Valve	1
EB15007	10/04/2014	Hydraulic Tank Level Sensor Pneumatic Tubing	1
EB15008	19/09/2015	Water Pump Idler Pulley	1
EB15009	07/05/2015	Coaltram Service Sheets	1
EB15010	25/05/2015	Removal of Level indicator Lights from Scrubber Level Sensors	1
EB15011	01/06/2015	CT08 Boom Top Reinforcing Plate	1
EB15012	20/06/2015	Coolant Loss and Engine Oil Pressure Test Tap	1
EB15014	28/07/2015	Float Sensor Shaft Upgrade	1
EB15015	03/09/2015	Nickel Plated ExDES Components	1
EB15016	28/10/2015	MONEx Scrubber Floats	1
EB15017	11/11/2015	C7 Engine Timing Sensor	1
EB15018	20/11/2015	Coaltram Service Sheets	1
EB16001	14/04/2016	CT08-CT10LP Boom Stiffening Upgrade	1
EB16002	14/04/2016	MONEx Battery Overhaul	1
EB16003	14/04/2016	MONEx Display Overhaul	1
EB16004	22/09/2016	Service Life of MONEx Equipment	1
EB16005	05/09/2016	Data Logger for FLP1 Throttle Watchdog System	1
EB16006	19/12/2016	Spring Washers for Driveline	1
EB17001	21/02/2017	COALTRAM Service Sheets	1
EB17002	26/04/2017	CT08-CT10LP Lift Cylinder Anchor Point	1
EB17003	05/05/2017	COALTRAM Rear Tow Hitch Allowable Vertical Load	1
EB17005	30/06/2017	COALTRAM® Ex Equipment Compatibility List	1
EB17006	30/06/2017	COALTRAM® Ex Compliance Audit	1
EB18003	21/06/2018	MONEx Piezo Actuated Valve Parts Consolidation	1
EB18005	23/10/2018	Exhaust Conditioner Level Float Update	3
EB18006	27/11/2018	TBS Brake Pedal Update	1
EB20001	23/01/2020	COALTRAM QDS Lock Cylinder Circuit	1
EB20003	03/07/2020	COALTRAM Service Sheets Update	1
EB20004	29/07/2020	COALTRAM Electrical Cable Protection Sleeves	1
EB23001	24/02/2023	COALTRAM Service Sheets Update	1

Technical Bulletins			
Doc #	Date	Description	Rev #
TBSA-0502	28/02/2008	CT10 - Check Brake Wear	1
CTTB-11-001	02/12/2011	Stick Steering Lever Mechanical Stops on Atlas Copco Coaltram Utility Vehicles	1
TB12001	16/11/2012	Exhaust Leak at the Exhaust Conditioner to Exhaust Pipe Fixed Joint	1
TB13001	21/10/2013	Park Brake Valve – Failure to Apply	1
TB13002	21/10/2013	Exhaust Gas Test Port	1
TB13003	19/11/2013	Isolation Air Reservoir and Check Valve	1
TB14001	20/05/2014	HEP Solenoid	1
TB14002	03/07/2014	Throttle Sensor	1
TB15001	12/03/2015	Accelerator to display software upgrade	1
TB15002	12/03/2015	Accelerator pedal position mechanical upgrade	1
TB15003	12/03/2015	Accelerator pedal position - Hardware upgrade	1
TB15004	06/05/2015	Throttle Pedal Cover	1
TB15005	20/10/2015	Turbo Impacting on Methane Junction Box	1
TB15006	11/11/2015	Park Brake Valve Scheduled Replacement	1
TB15007	21/12/2015	Brake Pedal Piston Pin Retaining Clips	1
TB15008	21/12/2015	Throttle Pedal Spring	1
TB16001	08/03/2016	Crowd cylinder Gland Bush Bolt Failure	1
TB17001	10/02/2017	HA108 Footswitch Enclosure	1
TB17002	22/08/2017	Steer circuit pressure filter	1
TB17003	29/08/2017	COALTRAM® Critical Components	1

Safety Bulletins			
Doc #	Date	Description	Rev #
SB13001	4/04/2013	Transmission cover not latched securely leading to injury	1
SB14001	16/05/2014	Oil ingress into ECUEx	1
SB14002	30/05/2014	Cap screw failures	1
SB15001	9/01/2015	Methane Air safety solenoid	1
SB15002	11/02/2015	Steer Amplifier Valve	1
SB15003	9/03/2015	Erratic Accelerator Operation	1
SB15004	9/03/2015	Engine Cranking	1
SB15005	4/05/2015	Uninitiated Engine Speed (Final Document)	1
SB19002	10/09/2019	Jel Seat Dampener Failures	1
SB20001	14/08/2020	Non-conforming Fuel Shutdown Cylinders	1
SB23001	16/08/2023	COALTRAM CT08/CT10LP Crowd Cylinder Failures	2

Safety Alerts			
Doc #	Date	Description	Rev #
SA17001	1/07/2017	Potential concerns regarding NTMS Methane Systems	1