

GEN (General)			
Doc #	Date	Description	Rev #
GEN2006-TBSA-01	20/07/2006	Pilot Control Vale Failure	0
GEN2008-TBSA-01	04/03/2008	Failed Door Latch Interlock Valve	0
GEN2008-TBSA-03	09/09/2008	Operator Covered in Hydraulic Oil due to Hydraulic Hose Failure	0
GEN2009-TBSA-01	23/03/2009	Fan Hub Failure	0
GEN2009-TBSA-02	27/05/2009	Mine Loader Driveshaft Centre Bearing Failure	0
GEN2009-TBSA-03	04/06/2009	Possible Oil Injection Occurrence	0
GEN2010-TBSA-02	09/09/2014	Using Genuine OEM Components	1
GEN2010-TBSA-03	01/03/2011	Pneumatic Horn Circuit	1
GEN2010-TBSA-04	23/05/2013	Exhaust Conditioner Makeup Tank Exhaust Check Valve	2
GEN2010-TBSA-05	18/02/2010	Mine Loader Front Driveshaft Centre Bearing Failure	0
GEN2011-TBSA-02	01/02/2011	Steer Pressure Reducing Valve	0
GEN2012-TBSA-03	07/11/2012	Setco / CSE Ex d Junction Box	0
GEN2014-TBSA-01	11/09/2014	Pneumatic Circuit	0
GEN2014-TBSA-02	11/09/2014	PTO Return Filter Housing Guard	0
GEN2014-TBSA-03	05/09/2014	Transmission & Torque Converter Lubrication	0
GEN2015-TBSA-02	20/02/2015	Tilt Cylinder Failure	0
GEN2015-TBSA-03	30/04/2015	Rear Differential Mounting Bolt	0
SB23002	15/12/2023	JUG-A-0 Hydraulic Adjustable Canopy Incident	1

DES (Diesel Engine System)			
Doc #	Date	Description	Rev #
DES2007-TBSA-01	02/02/2007	Collapsed Blowers Drive Snout Bearings	0
DES2007-TBSA-03	09/11/2007	Failed Electric Solenoid Valve due to water ingress in safety circuit	0
DES2009-TBSA-02	14/08/2009	Machine failed to shutdown on StopRun Valve and Emergency Shutdown Valve	0
DES2010-TBSA-01	17/08/2010	Heavy Duty Air Intake Filter Element Cleaning	0
DES2010-TBSA-02	25/08/2010	Supercharged J08C JUG-A-0 ULUV Air Intake Filter Maintenance	0
DES2011-TBSA-01	31/01/2011	Bypassing the JUG-A-0 Diesel Engine Shutdown System (Nautitech)	0
DES2011-TBSA-06	29/02/2012	DPM Filter Fire	1
DES2011-TBSA-08	11/02/2014	Diesel Engine system-Inlet Manifolds	1
DES2012-TBSA-03	20/08/2012	NTMS Methane Shutdown Systems	0
DES2013-TBSA-01	20/11/2013	Machine Shutdown System-Methane Bypass Switch Box	0
DES2014-TBSA-02	11/09/2014	MDR074246DES Inlet Manifold Flametrap Housing Fasteners	0
DES2014-TBSA-03	05/09/2014	VLI DES Intake Flametrap Assemblies	0
DES2014-TBSA-04	15/09/2014	Low Water Test Valve Change	0
DES2014-TBSA-05	04/11/2014	MDR074246DES Design Registration Alteration	0
DES2014-TBSA-07	19/12/2014	Nautitech Methane Shutdown Systems	0
DES2015-TBSA-01	15/04/2015	DES Gaskets - Using OEM Components	0
DES2015-TBSA-02	01/05/2015	DES Control Systems - Safety Critical Components	0
DES2016-TBSA-03	05/12/2016	MDR074246 DES Upgrade of strangler valve	0
DES2016-TBSA-04	05/12/2016	MDR114991 DES Upgrade of strangler valve	0
DES2017-TBSA-03	17/02/2020	DES Control Systems - Safety Critical Components	1
DES2017-TBSA-04	31/08/2017	MDR 074246 DES – Mechanical Exhaust Flametrap	0

TBS (Transport Braking System)			
Doc #	Date	Description	Rev #
TBS2008-TBSA-01	07/04/2008	Notification of Park Brake Failing to Apply	0
TBS2008-TBSA-02	28/09/2008	Park Brake Failed to Operate	0
TBS2009-TBSA-02	13/05/2009	Failures of JUG-A-0 ULUV brake pedal linkage	0
TBS2009-TBSA-03	31/10/2013	Brake Valve Failure	1
TBS2013-TBSA-01	19/09/2013	Unplanned Movement	1