



## **Technical Bulletin / Safety Alert**

**Unique ID No:** GEN2010-TBSA-02

**Rev:** 1

(This document supersedes all previous versions of GEN2010-TBSA-02)

**Subject:** Using Genuine OEM Components

**Date:** 9<sup>th</sup> September 2014

**Applicable to:** All VLI JUG-A-0, Drifrunner & Brumby Machines

**Details of Revision:** 0. Original Issue  
1. Update Company details and reissue.

**Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.**

### **Description:**

It has come to the attention of VLI that some equipment owners / end users could be using components that may negatively impact machine safety, reliability and performance as designed.

### **Recommendations:**

It is our duty to inform all owners / end users of VLI supplied equipment that the use of non OEM components may affect the design integrity and / or design registration compliance status of the equipment including safety critical systems.

**VLI recommends the use of genuine OEM components only.**

Please ensure this document is circulated to all relevant personnel within your organisation.

Should you have any further queries please contact your VLI Representative.

Beresfield  
8 Balook Drive  
Beresfield NSW 2322  
P: +61 2 4964 2300  
F: +61 2 4028 6796

Mackay  
6 Fursden Street  
Glenella QLD 4740  
P: +61 7 4942 7495  
F: +61 7 4942 4944

Emerald  
44 Industrial Drive  
Emerald QLD 4720  
P: +61 7 4987 5011  
F: +61 7 4987 4711

Unanderra  
3 Investigator Drive  
Unanderra NSW 2526  
P: +61 2 4220 9400  
F: +61 2 4272 5530

Mudgee  
24A Industrial Avenue  
Mudgee NSW 2850  
P: +61 2 6372 9847  
F: