

ENGINEERING BULLETIN

Ref Document No.	EB24001	Issue No.	1
Subject	COALTRAM® Service Sheets Update		
Release Date	23 rd August 2024		

Purpose – Advise COALTRAM® owners and operators of updated mechanical service sheets for maintenance of the COALTRAM®.

Applicability – All in service COALTRAM® models – CT08, CT10, CT10LP

Information

PPKME are continually looking to improve and tailor our OEM service sheets to include necessary tasks and inspections for our equipment.

Selected updates to the COALTRAM® service sheets are summarised on page 2.

Recommendations

PPK recommend reviewing maintenance procedures against those recommended in the attached service sheets.

Engineering Department

PPK Mining Equipment Pty Ltd

T: +612 4964 5400

www.ppkme.com.au

Document ID	Version No.	Page Ref.	Description
DD-020 Code A – Daily	8-1023	-	[No changes]
DD-021 Code B - Weekly/50hr	11-0824	8 of 11	Added CT08/CT10LP crowd cylinder checks
		11 of 11	Added autolube grease cartridge P/N 5520001696
DD-022 Code C- Monthly/250hr	11-0824	10 of 14	Added CT08/CT10LP crowd cylinder checks
		14 of 14	Added autolube grease cartridge P/N 5520001696
DD-023 Code C1 – 3 Monthly/500hr	15-0824	10 of 15	Added CT08/CT10LP crowd cylinder checks
		15 of 15	Added autolube grease cartridge P/N 5520001696
DD-024 Code C2 – 6 Monthly/1000hr	16-0824	4 of 17	Added inspection of engine breather hose
		11 of 17	Added CT08/CT10LP crowd cylinder checks
		17 of 17	Added autolube grease cartridge P/N 5520001696
DD-025 Code D - Yearly/2000hr	16-0824	5 of 19	Added inspection of engine breather hose
		12 of 19	Added CT08/CT10LP crowd cylinder checks
		19 of 19	Added autolube grease cartridge P/N 5520001696
DD-026 Code D1 – 2 Yearly/4000hr	16-0824	5 of 19	Added replacement of engine breather hose
		12 of 19	Added CT08/CT10LP crowd cylinder checks
		19 of 19	Added autolube grease cartridge P/N 5520001696
		19 of 19	Added engine breather hose P/N 5520001806
DD-027 Code D2 8000hr–	16-0824	5 of 23	Added replacement of engine breather hose
		15 of 23	Added overhaul/replacement of lift, crowd, hitch cylinders
		22 of 23	Added autolube grease cartridge P/N 5520001696
		22 of 23	Added front frame split cap bolt kits P/N 5520009361 and 5520009362
		22 of 23	Added engine breather hose P/N 5520001806