

Technical Bulletin / Safety Alert

Unique ID No: DES2010-TBSA-01 Rev: 0

Subject: Heavy Duty Air Intake Filter Element Cleaning

Date: 17/08/2010

Applicable to: All JUG-A-0, Driftrunner & Brumby Air Intake Filters

Note: Minimum PPE required to carry out any inspections contained in this TBSA shall be protective clothing & footwear, safety glasses, hearing protection & any site specific requirements. A JSA or equivalent should be carried out prior to performing these tasks.

Description:

It has come to the attention of Valley Longwall International Diesel Division (VLIDD) that some equipment owners / end users could be using heavy duty air filter elements that have been subject to a cleaning process.

Recommendations:

VLIDD does not recommend cleaning of air filter elements, and in line with our supplier's warranty policy, does not warrant air filter elements once they have been cleaned. This is because VLIDD has no control over the filter cleaning process.

Supporting Documentation:

Please refer attached Technical Bulletin from Donaldson for further information.

Please ensure this document is circulated to all relevant personnel within your organisation.

DES2010-TBSA-01 Page 1 of 2

Should you have any further queries please contact your VLI Diesel Representative.

Tomago Operation 28 Old Punt Road 20 Shipley Drive 6 Fursden Street 25 Hawkins Place Clenella QLD 4740 Emerald QLD 4720 P: +61 2 4913 7500 P: +61 2 4964 8919 P: +61 2 4932 1722 P: +61 7 4942 7495 P: +61 7 4987 4711

DES2010-TBSA-01 Page 2 of 2